

कार्यालय अधिशासी अभियन्ता
प्रान्तीय खण्ड, लो०नि०वि० मेरठ।



पत्रांक 2404 / NBC
सेवा में,

दिनांक: 27/7/25

मुख्य विकास अधिकारी
मेरठ।

विषय:- बालेराम बृजभूषण सरस्वती शिशु मन्दिर, डी ब्लॉक, शास्त्री नगर मेरठ के
नैशनल बिल्डिंग कोड के प्रमाण-पत्र के सम्बन्ध में।

संदर्भ :- आपका पत्र सं० 769/एस०डी०-सी०डी०ओ०/2025 दिनांक 12.06.2025

महोदया,

उपरोक्त विषयक दो मंजिल भवन का नैशनल बिल्डिंग कोड-2005 के अनुसार
प्रमाण-पत्र निर्गत करने हेतु अधिकृत अवर अभियन्ता/सहायक अभियन्ता द्वारा प्रदत्त
प्रमाण-पत्र संलग्न कर आवश्यक कार्यवाही हेतु प्रेषित है।

संलग्न :- प्रमाण-पत्र दो प्रतियों में।

मुख्य विकास अधिकारी
मेरठ

03.7.25

पत्रांक /

दिनांक.....

प्रतिलिपि :- सहायक अभियन्ता- प्रा०ख०, लो०नि०वि०, मेरठ को सूचनार्थ प्रेषित।

प्रतिलिपि :- अवर अभियन्ता (प्रा०), प्रा०ख०, लो०नि०वि०, मेरठ को सूचनार्थ प्रेषित।

अधिशासी अभियन्ता
प्रान्तीय खण्ड, लो०नि०वि०,
मेरठ

अधिशासी अभियन्ता
प्रान्तीय खण्ड, लो०नि०वि०,
मेरठ

BUILDING SAFETY CERTIFICATE**No.****Date :-**

It is certified that the existing building of Bale Ram Brij Bhushan Saraswati Shishu Mandir, D-Block, Shastri Nagar, Meerut at Tehsil -Sadar, Meerut is having block(s)/Floor (s) as per details below:

Details of Block(s) in school	Block (1)
Detatils of Floor (s) in Block	Ground +2

The building is owned/occupied by Bale Ram Brij Bhushan Saraswati Shishu Mandir, D-Block, Shastri Nagar, Meerut have complied with the Building safety requirements in accordance with National Building Code Rules and verified by the officers concerned of Public Works Department, District Meerut on and that the building/premises is fit for accupancy for running school with effect from 02/July/2025 for a period of THREE (03) Years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1- The School will be responsible for proper functioning of fire Safety equipments.
- 2- The School will be responsible for all safety Parameters of building structure.
- 3- The School will be responsible to comply all NBC Parameters in future if any structural changes will be done after issuance of this certificate.
- 4- In future if any problem regarding NBC arises, the school will be held completely responsible and the Department shall not be held responsible because this certificate is issued only on the basis of visual inspection.
- 5- Strength & Stability of Building depends on proper periodic Repair & Maintenance of the building for which institution will be solemnly responsible.
- 6- This Certificate is issued on the basis of Form for certificate for structural design sufficiency, Form for Supervision, Form for Certificate for execution of work as per structural safety requirements and Form for Completion certificate provided by designer/Architect.
- 7- This Certificate will be deemed invalid if any alteration is done in layout plan and design of building in future.

Issued on 02-07-2025 at Meerut by.

Signature with seal :

02/07/25
Assistant Engineer
Provincial Division PWD,
Meerut

Name : Er. Ankit Kumar

Designation : Assistant Engineer

Name & Address of Department/Office : P.D., PWD, Civil Lines, Meerut, U.P

Note : This Certificate should be signed/issued by Assistant Engineer & above officer of concerned Govt. Department Only.